BEFORE THE 1 POLLUTION CONTROL HEARINGS BOARD 2 STATE OF WASHINGTON 3 IN THE MATTER OF BYRON J. SMITH, d.b.a. Thayer Apartments, 4 Appellant, 5 6 vs. 7 PUGET SOUND AIR POLLUTION CONTROL AGENCY, 8 Respondent. 9

10

11

12

13

14

15

16

17

18

PCHB No. 322

FINDINGS OF FACT, CONCLUSIONS AND ORDER

This matter, the appeal of a \$50.00 civil penalty for an alleged smoke emission violation of respondent's Regulation I, came before two members of the Pollution Control Hearings Board (Walt Woodward, presiding officer, and Mary Ellen McCaffree) at a formal hearing in the Washington Commerce Building, Seattle, Washington, at 9:30 a.m., October 4, 1973.

Appellant appeared pro se; respondent appeared through its counsel, Keith D. McGoffin. Shirley W. Marshall, Seattle court reporter,

recorded the proceedings.

Witnesses were sworn and testified. Exhibits were admitted. Arguments were made.

From testimony heard, exhibits examined and arguments considered, the Pollution Control Hearings Board makes these

FINDINGS OF FACT

I.

At about 9:40 a.m. on March 15, 1973, from the boiler stack of the Thayer Apartments, 414 E. Pine Street, Seattle, King County, there was emitted for at least seven consecutive minutes black smoke in shade of No. 5 on the Ringelmann Chart.

II.

Section 9.03 of respondent's Regulation I makes it unlawful to cause or allow an air contaminant emission for more than three minutes in any one hour of a shade darker than No. 2 on the Ringelmann Chart.

III.

An inspector on respondent's staff, after observing the above-described emission, issued Notice of Violation No. 7656 to appellant. Subsequently and in connection therewith, appellant was served with Notice of Civil Penalty No. 751 in the amount of \$50.00, being one-fifth of the maximum amount which respondent may invoke for a violation of its Regulation I. That penalty is the subject of this appeal.

IV.

Immediately upon being notified of the alleged violation, appellant stopped the operation of the boiler furnace and summoned a repairman who corrected the mechanical maladjustment which had caused the emission.

FINDINGS OF FACT,
CONCLUSIONS AND ORDER

FINDINGS OF FACT, CONCLUSIONS AND ORDER

in these proceedings.

26

27

W. A. Gissberg, the other member of this Board, did not participate